



Rocky Flats Environmental Technology Site
P.O. Box 464
Golden, Colorado 80402-0464
Phone: (303) 966-7000



November 11, 1998

CORRES. CONTROL
LTR. NO.

98-RF -

F. A. Casella
Manager
Event Investigation and Reporting
Building T111A

EXTENSION OF ALARM RESPONSE PROCEDURES FOR BUILDINGS 774, 891, AND 995 – TWO-067-98

Water Operations is requesting an extension of the deliverable date for Task 4c-1 of the *Corrective Action Plan for Event Investigation of Building 374 Acid Spill on Dock 8*. This is due to not receiving the final results of the assessment report until October 29, 1998, in order to determine if Alarm Response Procedures (ARP) are warranted in facilities that were assessed. It has been determined that Building 891, which was not included in the assessment report also requires (ARP's). A new completion date of January 29, 1999 is requested. This task entails the creation of three separate Alarm Response Procedures for Buildings 774, 891, and 995. The procedure development has been initiated, but requires development of separate response flowcharts for each of the alarms in the buildings. The additional development time includes a review and comment period along with comment resolution.

If you have any questions concerning this correspondence, please contact me.

T. W. Overlid
T. W. Overlid
Director
Technical Support

TW0\wkg

Authorized Classifier
Signature:

DOCUMENT CLASSIFICATION

REVIEW WAIVER PER

Exemption # CEX-010-98

Date: _____

IN REPLY TO RFP CC NO.:

ACTION ITEM STATUS:

___ OPEN ___ CLOSED
PARTIAL

ULTRAPROVALS:

Orig. & Typist Initials:

ADMIN RECORD
IA- IA-A-00095